

PSU CABLE CONNECTION GUIDE




Accessories


PSU Screw




Cable Tie




20+4 Pin




20+4 Pin → Motherboard 24-pin connector




CPU 4+4 Pin




CPU 4+4 Pin → CPU / EPS power connector






PCIe 6+2 Pin




PCIe 6+2 Pin → Graphics card PCIe power connector




SATA




SATA → SSD / HDD / Fan hub / ARGB controller




MOLEX



MOLEX → Legacy peripheral device / fan accessory



PCIe5.0 | PCIe5.1



PCIe5.0 | PCIe5.1 → High-power graphics card power connector

PSU Safety Notice

Use only the cables supplied with this PSU. | Do not mix cables from other power supplies. | Make sure all connectors are fully inserted.
Do not open the power supply casing. | Keep the PSU away from moisture and high temperature. | Turn off the power before connecting or removing cables.